M/V EMPRESS OF THE NORTH - GROUNDINGON 05/14/2007

MISLE ACTIVITY NUMBER: 2929818
ORIGINATING UNIT: SECTOR JUNEAU
MISLE ACTIVITY OWNER: SECTOR JUNEAU
MISLE ACTIVITY CONTROLLER: SECTOR JUNEAU
MISLE CASE NUMBER: 349045

I. INCIDENT BRIEF

On 14 May 2007 at 0128 the M/V grounded on Rocky Island, AK. Vessel was carrying 206 passenger and 75 crewmembers. Vessel immediately began to take on water. Chief Engineer reported water in the forward chain locker, voids 1-3 & crew accommodation deck. Master ordered abandon ship and all passengers were safely evacuated to responding good Sam vessels. Passengers were transferred to CGC Liberty and then transferred to the AMHS vessel Columbia where they were taken to Auke Bay, AK. Vessel was able to transit back to Auke Bay, AK and moored at the AMHS dock there. Initial damage survey was completed with hull penetrations all along the starboard side. Also, the propellers on the starboard side "z-drive" were missing. Alcohol & drug testing were completed for all on watch personnel and the Master.

Comprehensive initial investigation completed including securing physical evidence & conducting on-watch witness interviews. NTSB responded to assume lead role in investigation. Case pends.

Comprehensive underwater survey is complete. CG-2692 received from the company. Damages are currently estimated to be \$4,000,000.00.

II. EXECUTIVE SUMMARY

Incident Summary

On 14 May 2007 at 0128 the M/V grounded on Rocky Island, AK. Vessel was carrying 206 passenger and 75 crewmembers. Vessel immediately began to take on water. Chief Engineer reported water in the forward chain locker, voids 1-3 & crew accommodation deck. Master ordered abandon ship and all passengers were safely evacuated to responding good Sam vessels. Passengers were transferred to CGC Liberty and then transferred to the AMHS vessel Columbia where they were taken to Auke Bay, AK. Vessel was able to transit back to Auke Bay, AK and moored at the AMHS dock there. Initial damage survey was completed with hull penetrations all along the starboard side. Also, the propellers on the starboard side "z-drive" were missing. Alcohol & drug testing were completed for all on watch personnel and the Master.

Comprehensive initial investigation completed including securing physical evidence & conducting on-watch witness interviews. NTSB responded to assume lead role in investigation. Case pends.

Comprehensive underwater survey is complete. CG-2692 received from the company. Damages are currently estimated to be \$4,000,000.00.

Incident Involved: Marine Casualty, Reportable

Level of Investigation: Formal

IMO Classification: Serious Incident

USCG Classification: Major Marine Casualty Was this a Serious Marine Incident? Yes

Was a Marine Board Convened by Commandant? No

Personnel Casualty Summary

Total Missing = 0
Total Dead = 0
Total Injured = 0
Total at Risk, Not Injured = 0

Total People at Risk = 0

Other Personnel (Not at Risk) = 281

Vessel(s) Status Summary

Actual Total Loss(es) = 0 Total Constructive Loss, Salvaged = 0 Total Constructive Loss, Unsalvaged = 0 Damaged = 1 Undamaged = 0

Property Damage Summary/Total Damage

Vessel(s) = \$4000000 Cargo = \$ Facility(s) = \$ Other = \$

Waterway Mobility Summary

Vessel Delays (including speed restrictions): None

^{*} Includes estimates

III. ACTIONS IN RESPONSE TO THIS REPORT

Actions on Recommendations

Safety Alerts

IV. FINDINGS OF FACT

Subjects of the Investigation

Vessels. The following vessels were subjects of this investigation. Particulars for each vessel follow.

Vessel Name: EMPRESS OF THE NORTH

Flag: UNITED STATES

Vessel Identification Number: 1140867 Call Sign: WDB4791 Status: Damaged

Role: Involved in a Marine Casualty

Vessel Class, Type, Sub-Type: Passenger Ship, River Cruise Vessel, General

(More Than 6, Gross Tonnage < 100)

Gross Tonnage(GRT):

Net Tonnage(NRT): Deadweight Tons:

Length: 299.3

Home/Hailing Port:

 Keel Laid Date:
 02/07/2002

 Delivery Date:
 08/07/2003

Place of Construction: FREELAND, WA, UNITED STATES
Builder Name: NICHOLS BROS BOAT BUILDERS INC

Propulsion: Diesel Electric

Horsepower: 6000

Master:

Classification Society: AMERICAN BUREAU OF SHIPPING

Owner: EN BOAT LLC

1071 camelback street newport beach, CA, 92660

US

Operator:

Inspection Subchapter: H

Most Recent Vessel Inspection Activity: 2826281, 02/17/2007 9:00:00 AM

Current Certificate of Inspection: Issued on 02/17/2007 2:16:09 PM, by Sector

Portland

Facilities. The following facilities were subjects of this investigation. Particulars for each facility follow.

Parties and Organizations. The following people and organizations were subjects of this investigation.

CACCIOTTI, MARINO RICARDO

Status: Not at Risk

Role: Subject of Investigation

Gender: Age: SSN: Birth Date: Email Address: Phone Number(): Address(Home/Primary Residence):	22
Comments:	US 3rd Mate
ORGAIN, DALE RAYMOND	
Status:	Not at Risk
Role:	Subject of Investigation
Gender:	
Age:	
SSN:	
Birth Date:	
Email Address:	
Phone Number(Phone Number): Address(Home/Primary Residence):	
Address(Home/Himary Residence).	·
Comments:	

Drug and Alcohol Testing. The following people have been determined by the Coast Guard, Law Enforcement Personnel, and/or the Marine Employer to have been directly involved in a Serious Marine Incident as defined in 46 CFR 4.03-2:

Response Resources. The following incident response resources were subjects of this investigation.

Resource Name: HC130H - 1700

Resource ID: 1700

Kind: Sub-Kind: Type:

Resource Name: HH60J - 6002

Resource ID: 6002

Kind: Aircraft (Helicopter)
Sub-Kind: SAR/Law Enforcement

Type:

Resource Name: HH60J - 6005

Resource ID: 6005

Kind: Sub-Kind: Type:

Resource Name: HH60J - 6024

Resource ID: 6024

Kind: Aircraft (Helicopter)

Sub-Kind: Type:

Resource Name: HH60J - 6026

Resource ID: 6026

Kind: Sub-Kind: Type:

Resource Name: MLB47 - 47261

Resource ID: 47261 Kind: Vessels

Sub-Kind: SAR/Law Enforcement Vessel

Type:

Resource Name: RBS - 25446

Resource ID: 25446 Kind: Vessels

Sub-Kind: SAR/Law Enforcement Vessel

Type:

Resource Name: USCGC LIBERTY

Resource ID: WPB 110 Kind: Vessels

Sub-Kind: SAR/Law Enforcement Vessel

Type:

Other Subjects. The following were subjects of this investigation.

Waterway Segment(s). The following waterway segment(s) were subjects of this investigation.

ICY STRAIT

Role: Location Local Name:

Description: ICY STRAIT, AK

Incident Information

Location(s).

DescriptionLatitudeLongitudeIcy Strait: ICY STRAIT58 10.4 N135 03.5 W

Sequence of Events.

05/14/2007 1:28:00 to 05/14/2007 1:28:00 (Known): Vessel grounded on Rocky Island. Island had a properly working ATON installed.

Event Type: Grounding

Event Class: In marked channel

Event Subclass:

Location: Known; US Waters

Description: Icy Strait: ICY STRAIT

Latitude: 58 10.4 N Longitude: 135 03.5 W

Subject(s) and Details:

Name Type Status Role

EMPRESS OF THE Vessel Damaged Involved in a Marine

NORTH Casualty

Details Filed: Grounding Details

Type of Grounding: Hard Type of Bottom: Rock

Depth of Water:

Charted: Feet Actual: Feet Recorded: Feet

Part of Vessel Aground: Centerline Bow

Vessel Course:

Vessel Speed:
Steering Functional:
Propulsion Functional:
Hazard to Navigation:
ATON Survey Required:

Yes

True
Knots
Fully
Fully
Fully
Yes

Fuel On Board: Cargo On Board:

Cargo Name Quantity

Additional Information:

V. CAUSAL ANALYSIS

The Initiating Event of the Incident

Initiating Event:

Failures of Defense Against Subsequent Events in the Incident

VI. REFERRAL FOR ENFORCEMENT ACTION

The following referrals for enforcement action have been made as a result of this investigation and represent those instances where the Coast Guard has gathered evidence that indicates one or more alleged violations or offenses may have occurred. Any determinations as to whether or not one or more actual violations or offenses have occurred are documented in the appropriate Coast Guard enforcement activities.